Division of Health Care Facilities STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION

(X3) DATE SURVEY COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A, BUILDING: 01 - MAIN BUILDING B. WING _ TN1935 05/30/2017

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

THE MEA	ADOWS	044 COLEY DAVIS R ASHVILLE, TN 3722		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FUL REGULATORY OR LSC IDENTIFYING INFORMATIO	1	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
N 831	1200-8-608 (1) Building Standards (1) A nursing home shall construct, arrange maintain the condition of the physical plant the overall nursing home environment in sumanner that the safety and well-being of the residents are assured. This Rule is not met as evidenced by: Based on observations, the facility failed to maintain the overall physical plant. The findings included: 1. Observation on 05/30/2017 at 11:28 AM,	and uch a e	RECEIVED JUN - 2 2017 Health Care Facilities	
Division of H	revealed a 3 hour cross corridor wall (next A2) penetration above the drop ceiling (3 dicable bundles with mixed fire caulk. NFPA 101, 8.3.5 (2012 Edition) 2. Observation on 05/30/2017 at 12:36 PM, revealed 1 of 2 cross corridor smoke doors A7) did not close within the frame. NFPA 101, 8.3.3.1 (2012 Edition), NFPA 80 6.1.4.2 (2010 Edition) 3. Observation on 05/30/2017 at 12:45 PM, revealed panic hardware on a 3 hour fire racross corridor (by room A1). NFPA 101, 8.3.3.1 (2012 Edition), NFPA 80 (2010 Edition) The maintenance director was present whe deficiencies were identified and was later acknowledged by the administrator during the conference on 05/30/2017.	to RM ata line (by ated), 8.4.3		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE